



Attorney Docket No. 1837.1005
Cafc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Yasuhiro ICHIHARA et al.

Application No.: 10/688,967

ATTENTION

Confirmation No.: 4266

CERTIFICATE OF CORRECTION

Filed: October 21, 2003

BRANCH

U.S. Patent No.: 7,004,646

Batch No.:

Issued: February 28, 2006

For: RECEPTACLE TYPE OPTICAL TRANSMITTER AND/OR RECEIVER MODULE

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

*Certificate
AUG 16 2006
of Correction*

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Aug 14, 2006

By: 
Gene M. Garner, II
Registration No. 34,172

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

AUG 16 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7,004,646

DATED : February 28, 2006

INVENTOR(S) : Yasuhiro ICHIHARA et al.

Column 8, line 39, change "sockets" to --socket,--

Column 9, line 26, after "each" insert --other--

Column 10, line 23, after "board" insert --;--

Column 10, line 33, after "each" insert --other--

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 7,004,646

No. of add'l copies
@ 50¢ per page

⇒

AUG 16 2006